



Final Design Report Comments Response Matrix

Date:15.10.2024

Ref	Observation	Response
1.	Server Room on the Second Floor was not amended to include dividing wall	Amendments indicated on Drawings No. A1.5 and A1.6. Partition wall introduced to divide the Server Room into two spaces and another door; Server Room and Battery Room. BOQ amended to reflect this change. Bill No.5, Element No.2, Items B, G and K
2.	Innovation Hub and Nursery Room have no provision for suspended ceilings	Amendments indicated on Drawings No. A1.13 and A1.20; BOQ amended to reflect this change. Bill No.5, Element No.5, Item Q
3.	No provision made for painting of existing walls that may be dirtied during the works	Painting to make good all wall surfaces after the works are done is already covered in the BoQ under items described as "Existing plastered wall surfaces" Additions made for Ground Floor Area.
4.	Vents missing at Stores 01& 02 on Ground Floor and doors	Amendments made to Ground Floor Plan and Window Schedule. BOQ amended; Bill No.5, Element No.1, Item O1
5.	Missing Description of ironmongery on the Door Schedule	Door and Window Schedule amended to reflect Ironmongery details.
6.	Height of foldable doors on Ground Floor – Conference rooms	Amendments indicated on Drawings No. A1.3 BoQ amended to reflect this change. Bill No.5, Element No.1, item J
7.	Provision of tiles on Ground Floor – Storage rooms	Amendments made to BoQ to reflect this change. Bill No.5, Element No.1, item Q.
8.	Wooden Door on 3 rd Floor changed to be Aluminum and glass	Amendments made to BoQ to reflect this change. Bill No. 5, Element No.3, item E.
9.	Structural steel works for 04 th Floor and Roof Terrace	Amendments included to BoQs to provide shop drawings Bill No.5, Element No.4, Item F and Bill No.5, Element No.5, Item E.